

# Motor Vehicle Safety Inspection

## AIS Automotive Repair

5980 High Street

Folcroft, PA 19032

Phone: 555-555-5555

Pennsylvania Inspection Station Number AIS1

Registrant		Vehicle	
Pink, Jeffery & Kathleen 316 Saude Ave Glenolden, Delaware, PA 19036		2003 Dodge Ram Pickup VIN: 1D7HA16N53J676229 Plate: VWX0049      Registered: PA	
		Fleet Number:	Other
		Color:	07
		Expiration Month:	
Insurance			
GEICO GENERAL INSURANCE COMPANY		Policy: 0214719721	Expiration Date: 03/11/2009
Inspection			
Date Inspected:	11/10/2008	Mileage Last Inspection:	44,541
Work Order or Mechanic:	52	Current Mileage:	54,507
Inspection Number:	33	Safety Sticker Number:	A19-0369273
Inspection Type:	Annual Inside	Expiration Month/Year:	11/2009
		Emissions Sticker Number:	
Visual Anti-Tampering	Result	General Inspection Points	Result
Catalytic Converter	N/A	Registration Verified	Passed
Fuel Inlet Restrictor	N/A	Tires & Wheels	Passed
PCV Valve	N/A	Steering, Suspension	Passed
EGR Valve	N/A	Exhaust System	Passed
Air Pump	N/A	Fuel System	Passed
Evaporative Control System	N/A	Glazing & Mirrors	Passed
		Lights, Wiring & Switches	Passed
		Body, Doors & Latches	Passed
		Brake System	Passed
		Other	Passed
		Road Test	Passed
Brakes	Type	Thickness in 32nds of an Inch	Result
Left Front	Bonded	10	Passed
Left Rear	Bonded	3	Passed
Right Front	Bonded	10	Passed
Right Rear	Bonded	3	Passed
Tires	Tread Depth in 32nds of an Inch	Result	
Left Front	4	Passed	
Left Rear	4	Passed	
Right Front	4	Passed	
Right Rear	4	Passed	
Additional Information			
Inspected By		Signature	
Rick Dunmire			