



Voided Safety Sticker Report
AIS Automotive Repair - Station AIS1
Annual Inside - Campaign Year 2009 - Inspection Numbers 1 to 999

Sticker #	Inspection #	Work Order #	Date Issued	Status	VIN	Plate
AI9-0369242	2	23	10-09-2008	Voided	1YVHP80D365M71209	NOP0014
AI9-0369247	7	27	10-13-2008	Voided	1D4HS38ZX3F609988	JKL0035

Total Stickers Voided: 2